



BUREAU VERITAS



BV Ref.: GTS_2023_330472

Page 1 of 6

Inspection Report

Applicant : Qingdao Henger Shipping Supplies Co., Ltd.

Declared Commodity & Quantity : Pneumatic rubber fender
DIAMETER:1.2M, LENGTH:2.0M: 5PCS

Inspection date : NOV.03, 2023

Inspection Location : Jimo, Qingdao City, Shandong Province, China

Scope of Inspection : 1. Packing and Marking
2. Size checking (the overall L & D)
3. Overall visual inspection
4. Air tightness test to check for leakage

INSPECTION PERFORMED

Storage Condition:

At the time of our attendance at the factory, we found the fenders were placed in the manufacturer's open yard, in normal condition.

Packing:

The Fenders were in nude packing, with the chains and used tires around the fenders' body.

Marking:

The marking was printed on the body of fenders, details as below:

LUMUT PORT

Size checking:

According to client's requirement, total 5pcs of fenders were measured sizes, including the overall length and overall diameter, details as below:


| Size: D1.2X L2.0m | | |
|-------------------|-------------|-----------|
| Sample No. | Diameter(M) | Length(M) |
| 1 | 1.20 | 2.01 |
| 2 | 1.20 | 2.00 |
| 3 | 1.21 | 2.00 |
| 4 | 1.21 | 1.97 |
| 5 | 1.21 | 2.00 |

Remark:

- The measurement tools were provided by the factory without the calibration certificate, and the measurement was done approximately as shown in pictures here under. The result was for reference only.
- The measurement was checked at inflated 50kpa pressure.

Air tightness test to check for leakage:

According to client's requirement, the above mentioned 5 pieces of fenders were charged at pressure declared by 50KPa under BV inspector witness, then covered with the soap water on the surface of the fender to check the air leak



We now certify that the above inspection has been carried out according to Bureau Veritas General conditions and above findings are valid at time and place of inspection. The issuance of this inspection certificate does not release the contractual parties from their own responsibilities and the fulfillment of their obligations.



**BUREAU
VERITAS**

BV Ref.: GTS_2023_330472

Page 2 of 6

if any, as far as visually checked, it's found in normal conditions, after 1 hour, checked the pressure again, no obviously air leak was found visually.

Remark:

1. BV inspector only witnessed the process of testing according to the mill in-house test procedures at the client's request, and the responsibility therein for test procedures' compliance with the related standards, test result accuracy and reliability, equipment calibration, test engineer qualification etc, fully remains with the client and the factory.
2. The pressure gage was provided by the factory without the calibration certification, and the result was for reference only.

Overall visual inspection:

According to client's requirement, BV inspector found the above mentioned 5 pieces of fenders were in normal condition without obviously damage and scratches.

**Photo Report
Storage condition**



Packing




We now certify that the above inspection has been carried out according to Bureau Veritas General conditions and above findings are valid at time and place of inspection. The issuance of this inspection certificate does not release the contractual parties from their own responsibilities and the fulfillment of their obligations.



BUREAU
VERITAS

Marking



Pressure testing to check for leakage



We now certify that the above inspection has been carried out according to Bureau Veritas General conditions and above findings are valid at time and place of inspection. The issuance of this inspection certificate does not release the contractual parties from their own responsibilities and the fulfillment of their obligations.





BUREAU
VERITAS

BV Ref.: GTS_2023_330472

Page 4 of 6



Size checking




We now certify that the above inspection has been carried out according to Bureau Veritas General conditions and above findings are valid at time and place of inspection. The issuance of this inspection certificate does not release the contractual parties from their own responsibilities and the fulfillment of their obligations.




**BUREAU
VERITAS**

BV Ref.: GTS_2023_330472

Page 5 of 6



Overall visual inspection



We now certify that the above inspection has been carried out according to Bureau Veritas General conditions and above findings are valid at time and place of inspection. The issuance of this inspection certificate does not release the contractual parties from their own responsibilities and the fulfillment of their obligations.



**BUREAU
VERITAS**

BV Ref.: GTS_2023_330472

Page 6 of 6



Stone Zhu

Bureau Veritas Bivac Asian CRE (Shanghai) Inspection Co., Ltd.

We now certify that the above inspection has been carried out according to Bureau Veritas General conditions and above findings are valid at time and place of inspection. The issuance of this inspection certificate does not release the contractual parties from their own responsibilities and the fulfillment of their obligations.